

Total number of printed pages : 8

B. Tech
BENG 1201

Third Semester Examination – 2008

ELECTRICAL MACHINES

Full Marks – 70

Time – 3 Hours

*Answer Question No. 1 which is compulsory
and any five from the rest.*

*The figures in the right-hand margin indicate
marks for the questions.*

1. Answer the following questions : 2×10
- (a) What is the function of an 'interpole' in a d.c. machine ? Where it is situated in a d.c. machine and why its winding is connected in series with the armature winding ?

P.T.O.

- (b) Mention any two reasons for which a d.c. shunt generator may fail to build up voltage across its armature terminals.
- (c) Why the series field conductors are thicker and less in number in comparison to the shunt field conductors of a d.c. machine? Explain.
- (d) Draw the equivalent circuit of a single-phase transformer supplying full load at 0.8 power factor lagging. Name the various parameters of the equivalent circuit.
- (e) Draw the power angle characteristic of a cylindrical rotor three-phase synchronous motor neglecting its stator resistance. Find out the load angle for which the power developed becomes maximum.
- (f) Calculate the 'distribution factor' and 'pitch factor' of the 3-phase balanced winding having 54 stator slots, 6 poles and coil span of 8 slots.

- (g) Draw the curve showing variation in stator input current with variation in field current in case of a synchronous motor for 25% and 100% loads.
- (h) Calculate the 'slip speed' and 'slip frequency' of a 6-pole 3-phase induction motor drawing power from a 3-phase, 440 V, 50 Hz source and running at 970 rpm.
- (i) Explain, in brief, why the developed torque of a three-phase induction motor is zero at synchronous speed.
- (j) Draw the circuit diagram showing the connection of the main running winding and auxiliary starting winding of a single-phase induction motor using a capacitor for its starting purpose.
2. (a) A 250 V d.c. shunt motor takes a full load line current of 50 A. The armature and field resistances are 0.4 ohm and 250 ohms

respectively. The total brush contact drop is 2 V. The core and friction losses are 500 watts. Assume the stray load losses to be equal to 90 watts. Calculate the output and efficiency of the motor. 5

(b) Draw neatly the diagram of a 4-point starter of a d.c. shunt motor and explain its principle of operation. Which demerit of the 3-point starter is eliminated here? 5

3. (a) Explain the voltage build-up process in case of a d.c. shunt generator. What are the factors affecting this process? How can a d.c. shunt generator regain its lost residual field flux? 5

(b) A separately excited d.c. generator operating at a voltage of 'V' volts has an armature circuit resistance of ' R_a ' ohm. It has a constant loss of ' P_c ' watts. It delivers an armature current of ' I_a ' amperes. Derive the expression for the armature

current ' I_a ' for obtaining maximum generator efficiency. 5

4. (a) Derive an expression for the 'voltage regulation' of a single phase transformer in terms of its per unit resistance and per unit leakage reactance for a leading power factor load. For what value and nature of power factor, the voltage regulation will be zero? 5

(b) The parameters of the equivalent circuit of a single phase, 50 Hz, 200-kVA, 2300 V/230 V transformer are as follows:

HV winding resistance = 0.22 ohm. LV winding resistance referred to HV winding = 0.18 ohm. HV winding leakage reactance = 0.5 ohm. LV winding leakage reactance referred to HV winding = 0.5 ohm. Resistance representing core loss in the transformer referred to HV side = 15 kilo-ohm. The magnetizing reactance of the

transformer referred to HV side = 2 kilo-ohm. Determine the voltage regulation of the transformer operating at rated load with 0.707 lagging power factor. 5

5. (a) Explain how three single-phase two winding transformers can be connected in 'star-delta'? The source side is star connected. Show the connection diagram and draw the phasor diagram of induced voltages (both star and delta sides) for this connection. 4

(b) It is desired to have a 5 mWb maximum core flux in a transformer at 230 V and 50 Hz. Determine the required number of turns in the primary. 2

(c) A single-phase 50 Hz transformer takes 100 watts of power at 1 A and 230 V while operating at no-load. If the primary winding resistance is 0.55 ohm, find the core loss and the no-load power factor. 4

6. (a) Draw neatly the phasor diagram of a cylindrical rotor three-phase synchronous generator supplying rated power to a load at unity power factor. Show the mmf space phasor diagram and emf time phasor diagram together in the same figure and explain the various phasors briefly. 5

(b) A 250 MVA, 11 kV, 50 Hz, star connected three phase alternator has a synchronous impedance of $(0.13 + j1.87)$ ohms per phase. Find the no-load induced emf per phase while the generator is supplying rated full load at a power factor of 0.707 lagging. What is the load angle of the alternator under this condition? 5

7. (a) Explain why a three-phase synchronous motor has no self-starting torque. Describe any two methods of starting it. 5

(b) A 3 phase, 11 kV star connected synchronous motor draws a current of 70 A

from the mains. The effective per-phase synchronous impedance of the motor is $(0.5 + j5)$ ohms. Find the per-phase induced emf and load angle 'delta' for an operating power factor of 0.707 leading. 5

8. (a) The power input to the rotor of a 3-phase, 50 Hz, 6-pole induction motor is 100 watts. The rotor induced emf makes 120 revolutions per minute. Find slip, rotor speed, mechanical power developed, rotor copper loss and the torque developed. 5

(b) Develop, step by step, the per phase equivalent circuit of a three-phase induction motor from first principles like a single-phase or three-phase transformer. 5